

CASE HISTORY HONDA CRV ABS.



WE WERE ASKED TO INVESTIGATE THE ABS SYSTEM ON A 2001 HONDA CRV; THE WARNING LIGHT WAS ON ALL THE TIME. FAULT CODE INFORMATION REVEALED A CODE FOR MAIN RELAY FAILURE. FURTHER TESTING CONFIRMED THIS TO BE THE CASE. WE ATTEMPTED TO ORDER A NEW RELAY VIA OUR LOCAL MAIN DEALER THEY SUPPLIED A COMPLETE MODULATOR WHICH UPON INVESTIGATION WAS INCORRECT THE MAIN RELAY WAS INSIDE THE ELECTRONIC CONTROL UNIT (SEE BELOW)



THIS IS A TYPICAL HYBRID CIRCUIT THAT IS NOW USED IN MOST MODERN CARS AND IS NOT REPAIRABLE. THE COST OF THIS UNIT £1200 INC VAT