

## CASE HISTORY FIESTA 1.4

**VEHICLE FAULTS:-** Hesitation on light throttle 2000 rpm

**VEHICLE HISTORY:-** several dealer visits and no faults stored in ecu fault memory so vehicle must be o.k.

**TESTING:-** Our normal level one diagnostic checks revealed the cylinder head core plugs to be leaking into the spark plug well and the plugs and leads were badly corroded causing ht leakage and misfiring . see pictures :-



