

## CASE HISTORY MERCEDES ML

**VEHICLE FAULTS:-** Intermittent cutting out and non start and SRS light on .

**VEHICLE HISTORY: -** The vehicle had recently been repaired for the same fault .The repair had consisted of wiring repair to the fuel pump.

**TESTING:-** Testing procedures with our Autologic test equipment revealed that when the vehicle cut out the fuel pressure was lost test to drive the fuel pump proved unsuccessful .After stripping out the rear seats we found one of the worst repairs we have ever seen on wiring see picture below . Both the SRS wiring was damaged and the wiring to the fuel pump had been very poorly repaired. Repairing the SRS wiring, replacing the fuel pump with a new Wiring harness cured the fault.



